REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE

(ER 1130-2-3165)

PAGE OF 1

DATE: September 20, 2006

U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST TO: The Record FROM:

New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:

Raritan River to Arthur Kill Cut-Off Channel, New Jersey

MINIMUM DEPTHS IN **CHANNEL ENTERING FROM SEAWARD**

(Proponent: CECW-OM)

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT WIDTH LENGTH DEPTH			LEFT OUTSIDE QUARTER	LEFT INSIDE QUARTER	RIGHT INSIDE QUARTER	RIGHT OUTSIDE QUARTER
		(feet)	(nmiles)	(feet)	(feet)	(feet)	(feet)	(feet)
Raritan River to Arthur Kill Cut-off Channel	Map 51, Pg 1 & 2; 13 -24 Jul 2006	600	0.87	20	17.6	19.2	20.0	18.4

REMARKS:

- All depths are in reference to Mean Low Water (MLW)
- Channel shoaling
 - Shoaling exists along the left half of the channel commencing from the junction with Raritan River and continuing to a point approximately 700 feet south of RED NUN #2 EBB with minimum depth of 17.6 feet along the channel toe line
 - Shoaling, 500 ft long 150 ft wide, located in the right outside quarter channel beginning at the Raritan R. junction. Small spot shoaling exists along the right edge of this quarter 100 feet south from GREEN CAN #3.